From: Joseph Vitale

To: Geiger, William; Fatzinger, Travis T NAP; "David.S.Depolo@usace.army.mil"

Cc: <u>June Yeung; Walter J. Papp, Jr.; Joseph Caciola</u>

Subject: Metal Bank

Date: Tuesday, June 28, 2016 5:32:34 PM

Attachments: <u>image001.png</u>

Gentlemen:

To date, Creamer, through their subcontractor, has successfully tested 6 out of the 10 tie rods. This includes all of the tie rods in the "waler repair" area. Given that the tests have all passed to date and the testing subcontractor has conducted the tests to RA Consultants' satisfaction, we do not feel it is necessary for the Group's geotechnical consultant (RA Consultants) to be on site tomorrow. Therefore, RA Consultants are not planning to return to the site, unless a technical issue arises with the repair of the sheet pile wall requiring their attention.

Any questions, please do not hesitate to call.

Talk to you soon.

Regards,

Joseph P Vitale, PE, LSP

MS Civil Eng., MBA Principal Consultant Office 617 946 6115 Mobile 617 721 2766

jvitale@ramboll.com

Ramboll Environ

20 Custom House Street, Suite 800

Boston, MA 02110

www.ramboll-environ.com



My email addresss has changed to <u>jvitale@ramboll.com</u>. Please make a note of this in your contact records. I will continue to receive email at the <u>jvitale@environcorp.com</u> address.

This message contains information that may be confidential, privileged or otherwise protected by law from disclosure. It is intended for the exclusive use of the Addressee(s). Unless you are the addressee or authorized agent of the addressee, you may not review, copy, distribute or disclose to anyone the message or any information contained within. If you have received this message in error, please contact the sender by electronic reply to email@ramboll.com and immediately delete all copies of the message.